

PIPE FITTER JOINT APPRENTICESHIP AND TRAINING COMMITTEE
OF PIPEFITTERS LOCAL UNION NO. 211

TESTING (JAN-JUN): Tuesday, Wednesday & Thursday (7:30am to 10:30am & 1pm- 2pm)
TESTING (SEPT-NOV): Tuesday, Wednesday & Thursday (7:30am to 10:30am & 1pm- 2pm)
TESTING (JUL, AUG, DEC): Thursday (7:30am to 10:30am & 1pm- 2pm)

APPOINTMENT REQUIRED FOR TESTING/APPLICATION PROCESS

Interviews for Fall Semester are in July—NOTE: testing (December - early June.)
Interviews for Spring Semester are in December- NOTE: testing (July - mid Nov.)

APPLICATIONS ARE ISSUED AT TIME OF TESTING

1. Must be at least 18 years of age.
2. **REQUIRED Documents to take the test**
 - a. High School Transcripts or GED Certificate with Test Grades.
 - b. Birth Certificate, ID card, **and** Social Security Card (ALL 3 are required)
 - c. DD-214 (if applicable)
3. Must pass a Math Test with a grade of 72 or above and complete an OSHA 10 class.
4. Must appear for a personal interview with the Joint Apprenticeship and Training Committee when scheduled.

It's a 5 YEAR PROGRAM (10 SEMESTER)

Classes Location: 1301 W. 13 th St. Deer Park, TX 77536	Mailing Address: 1301 W. 13 th St. Deer Park, TX 77536	Phone: 713-649-0201 Fax: 281-479-3049
---	--	--

Type of Training: "Apprenticeship" (Classroom and On-The-Job Training)

Classroom Training: August thru December / January thru May
A minimum of 246 Hours per year is required.

Class Schedule: Two nights MONDAY/WEDNESDAY or TUESDAY/THURSDAY - 5:30 PM to 9:30 PM

Required Courses: Introduction to Pipe 1st Semester General Pipe Fitting 2nd Semester

Courses:

Template/Fabrication I & II	Welding I, II, & III	Drafting I & II
AC I & II	A/C Controls I & II	Rack & Tubing
Mechanical Lab	A/C Commissioning	Foreman Training
Rigging	Advanced Troubleshooting	Instrumentation, I & II

(Additional courses may be added at any time)

On-the-Job Training

Pipefitting
Air Conditioning
Welding

Locations

High Rise Bldg.
Industrial Plants
Pipe Fabrication Shops

Note:

You must have a minimum of 1700 hours per year of on the job training. A total of 8500 Work hours for the five years.

Normal Work Schedule:

Daytime eight (8) hours
5 days per week
Monday thru Friday

Installations of:

Screw Pipe
Solder Copper Pipe
Plastic Pipe
Welded Pipe

Rigging

Material Handling
Fabricating Pipe
Controls

THIS IS A NON-PROFIT PROGRAM

Student Cost: Tuition is Free

Books and Material required for the classroom are **NOT** free and must be paid on **the first day of school.**

Wages /Fringes: Paid by the employer, based on a percentage of the negotiated journeyman's rate.